

August 24, 1964

④ File

LINEAR PHASOLVER MEASURING ENGINE

STAT

The [ ] will be shut down for vacation from August 24 until after Labor Day, 8 September.

STAT

The pattern master which was received from [ ] August 3 was visually acceptable and has been measured by [ ] [ ] is out with the flu and [ ] was in the middle of reviewing the measurement data.

STAT

STAT

STAT

STAT

The patterns are not as good as they could be, but the question Pete is trying to resolve is whether they are good enough for submicron measuring. The first and second harmonic errors, if constant from pole to pole, will wash out electrically. Pete thinks that second harmonic errors are a result of bleeding during pattern exposure and development.

Pete's tentative opinion is that the patterns are good enough to achieve 1/4 micron measurement resolution and they probably should be sent on to [ ] to prepare the working pattern. He and [ ] however, will have to discuss this thoroughly after careful review of the measurement data.

STAT

STAT

A copy of [ ] instructions to [ ] is enclosed. It illustrates the pattern at double scale. This simple set of measurements generates so much data that it is a real chore to assimilate it and judge the pattern quality.

STAT

It is expected [ ] will take a month to prepare the working driver and then [ ] will require one to two months for setup and trial. It looks like the demonstration will not take place before November.

STAT

STAT

Since the [ ] has been doing a good job, I thought their other divisions might have applicable talents and their general brochure is enclosed. The only other possibility that I can see would be computer programs from [ ] It is extremely difficult, however, to use that type of service.

STAT

STAT

STAT

DDR - NOT A  
DUPE

Enclosures

INSTRUCTIONS FOR THE MEASUREMENT OF  
LINEAR PHASOLVER PATTERN CONSISTING  
OF 1000-2405 and 1000-2408

Pattern 1000-2405

1) Tabulate 21 consecutive measurements of sine wave height (Y axis) Vs. equal increments of .050 mm in X. The starting point should be the average of min. & max. values of Y.


This procedure is to be repeated a total of 3 times within this pattern as noted A, B, and C on page 2. A and B denote two non-adjacent sine waves near the center of the pattern. C is the same sine wave as A but near the end of the pattern.

2) Measure the quadrature (phase displacement) at one place on the pattern as shown at D on page 2.




Pattern 1000-2408

3) Tabulate 21 measurements as in 1) above 3 places, E, F, and G on page 2. E and F are two non-adjacent sine waves near the center of the pattern. G is the same sine wave as E but near the end of the pattern. Measure from datum line in plus Y direction only.\*

4) Measure the quadrature (phase displacement) in six places, three in each half of the pattern as shown in H, I, J and K, L, M.



STAT



↑  
→ X

Pattern shown  
2x Size. 208  
8/24/64